USE OF CALCIUM CHLORIDE IN CONCRETE IS PROHIBITED.

APPLIES TO FLOORS AND WALLS).

UNLESS OTHERWISE SHOWN, COORDINATE CONSTRUCTION JOINTS LOCATION

IMPAIR STRENGTH OF STRUCTURE AND TO MINIMIZE SHRINKAGE STRESSES.

PROVIDE DOWELS AS DIRECTED AND THOROUGHLY CLEAN AND ROUGHEN SURFACES BEFORE PROCEEDING WITH NEXT PLACEMENT (THIS REQUIREMENT

WITH THE CONTRACTING OFFICER. THEY MUST BE SO LOCATED AS TO LEAST

TYPICAL WELDED BAR SPLICE DETAIL

INCLUDING BLOCK JOINTS.

TYPICAL CMU SPALL REPAIR DETAIL

LICENSED

PROFESSIONAL

ENGINEER

No. 13255-S

CONSTRUCTION

DOCUMENTS

, <u>Ü</u>

DPERATIONS CENTER (
) IMPROVEMENTS
AND REPAIR DETAILS

0

SIRKHIMER EMERGENCY C UPGRADES AND STRUCTURAL NOTES

AS NOTED

CA-202313-C

STATE JOB NO.

FEDERAL PROJECT NO.

SHEET OF 123

S-501

4/30/2026

5



