


**Assessment of
Repair and Maintenance Needs**

**The State's War Memorials
And
Veterans' Cemeteries**



Prepared By
State of Hawaii
State Department of Defense,
Office of Veterans Services

February 28, 2014

Table of Contents

Title	Page
1. Executive Summary	2
2. Introduction	3
Purpose	4
Scope of Assessment	4
Methodology	5
3. Repair and Maintenance Findings	5
Oahu	6 - 17
Armed Forces Eternal Flame	7 - 8 (8a-8i)
Korean and Vietnam War Memorials	9 (9a-9f)
World War II Monument	10 - 11 (11a-11d)
Varsity Victory Volunteers Sculpture	12 - 13 (13a-13e)
Hawaii State Veterans Cemetery	14 - 15 (15a-15g)
29th Infantry Vietnam Veteran Memorial	16 (16a-16e)
Interstate H-2, Veterans' Memorial Freeway	17
Hawaii	18 - 28
Hilo Veterans Cemetery No. 1	18 - 19 (19a-19d)
Hilo Veterans Cemetery No. 2	20 - 21 (21a)
Yukio Okutsu Veterans Home	22 - 23 (23a-23b)
General Lyman Airport	24 (24a-24b)
Keaukaha Military Reservation (KMR) Armory	25 (25a)
Pahala Memorial	26 (26a-26b)
West Hawaii Veterans Cemetery	27 - 28 (28a-28i)
Maui	29 - 34
Makawao Veterans Cemetery	29 - 30
Hoolehua Veterans Cemetery on Molokai	31 - 32 (32a-32f)
Lanai Veterans Cemetery	33 - 34 (34a-34k)
Kauai	35 - 39
Kauai Veterans Cemetery	35 - 36 (36a-36h)
Kauai Veterans Memorial Hospital	37 - 38 (38a-38e)
Waimea War Memorial Swimming Pool	39 (39a-39d)

*** The numbers and alphabets within the parentheses are pictures of each site.**

Executive Summary

The ultimate purpose of Hawaii's war memorials is to honor those who made the supreme sacrifice in defense of our country's freedom. The goal of the Hawaii State-County Veterans' Cemetery system is to provide final resting place for veterans and their eligible family members. The report includes ratings for each of the eight State veteran cemeteries, eleven State memorial sites honoring our veterans and one veterans home. Seven of the above mentioned sites are located on Oahu, seven on Hawaii, one each on the islands of Maui, Molokai and Lanai and three on Kauai.

Act 63 passed by the Eighteenth Legislature, 1995, State of Hawaii and amended in 1997, tasks the Office of Veterans Services to: "Inspect every three years all state war memorials and veterans' cemeteries for repair and maintenance deficiencies, and report all repair and maintenance problems at these memorials and cemeteries to the adjutant general, comptroller, and the legislature prior to the start of the next regular session." The purpose of these inspections is to ensure that these war memorials and cemeteries are in good repair and worthy of the honor and respect due the memories of those they represent.

Inspection teams, using the Inspection Checklist, went to each of the twenty sites and performed a thorough evaluation. Each site was deemed to be either: excellent, good, or fair. An excellent site had no discrepancies and was clean and well maintained. A good site had minor discrepancies; however, it too was clean and fairly well maintained. A fair site required repair or maintenance. This may be ground maintenance, structural repair, replacement of the memorial or general cleaning and upkeep.

This report concentrated only on State war memorials and cemeteries within the Hawaii State-County Veterans' Cemetery system. The National Memorial Cemetery of the Pacific or Punchbowl as it is known, is a federally funded cemetery located on Oahu and was not included in this report.

Repair and Maintenance Findings

The following locations were rated as follows: Table 1. State Memorial and Veterans Cemeteries by "Condition".

Table 1

State Memorial and Veterans Cemeteries - Overall Condition of Site

Armed Forces Eternal Flame - Oahu	Good
Korean and Vietnam Memorials - Oahu	Good
World War II Monument - Oahu	Good

Varsity Victory Volunteers Sculpture - Oahu	Good
Hawaii State Veterans Cemetery - Oahu	Good
29th Infantry Vietnam Veteran Memorial - Oahu	Excellent
Veterans' Memorial Freeway - Oahu	Good
Hilo Veterans Cemetery Number 1 - Hawaii	Excellent
Hilo Veterans Cemetery Number 2 - Hawaii	Good
Yukio Okutsu State Veterans Home - Hawaii	Excellent
General Lyman Airport - Hawaii	Good
KMR Armory - Hawaii	Excellent
Pahala Memorial - Hawaii	Excellent
West Hawaii Veterans Cemetery - Hawaii	Excellent
Makawao Veterans Cemetery - Maui	Fair
Hoolehua Veterans Cemetery on Molokai - Maui	Fair
Lanai Veterans Cemetery - Maui	Good
Kauai Veterans Cemetery - Kauai	Fair
Kauai Veterans Memorial Hospital - Kauai	Fair
Waimea War Memorial Swimming Pool - Kauai	Fair

Introduction

The State's war memorials are intended to remind future generations of Hawaii's residents of our values and freedoms for which so many of our sons and daughters sacrificed their lives. The Hawaii State-County Veterans Cemetery system is the final resting place of our country's fallen heroes, comrades in arms, and their immediate family members. The ultimate goal of both the cemeteries and monuments is to honor the men and women who have served honorably in the armed forces of the United States.

Hawaii's State war memorials and veterans' cemeteries are our promise to veterans that their deeds, service, names will not be forgotten. In 1976, the legislature declared that the historical heritage of the state is among one of our most important assets. This sentiment was codified in section 6E-1 of the Hawaii Revised Statutes.

It is the State's policy to provide leadership in preserving, restoring, and maintaining historic property, and to engage in programs at all levels of Government that promote education, inspiration, pleasure, and enrichment for its citizens. These programs ensure the preservation and enhancement of historic property such as our memorials, veterans' cemeteries and veterans' homes for future generations.

Purpose of the Study

The purpose of this study as specified in Act 63, as amended: is to "inspect every three years, all state war memorials and veterans cemeteries for repair and maintenance deficiencies, and report all repair and maintenance problems at these memorials and cemeteries to the adjutant general, comptroller, and the legislature prior to the start of the next regular session." This will ensure that potential problems are detected and scheduled for repair as expeditiously as possible.

As required by the Act, this report is provided to the Adjutant General, the State of Hawaii Comptroller and the Legislature.

Scope of Assessment

In total, twenty locations were assessed. Included in the assessment were all war memorials, one freeway maintained by the State of Hawaii and eight veteran's cemeteries comprising the Hawaii State-County Veterans' Cemetery system. The numbers and location of war memorials including freeway and veterans cemeteries are shown in Table 2.

Table 2
State War Memorials and Cemeteries by Island

ISLAND	State War Memorials	Cemeteries
Oahu	6	1
Hawaii	4	3
Maui	0	1
Molokai	0	1
Lanai	0	1

Kauai	2	1
Total	12	8

Methodology

Office of Veterans Services (OVS) staff, members of the Advisory Board on Veterans Services or selected experts were asked to inspect each site using an inspection checklist. The checklist contained fourteen items used to identify any maintenance, repair, American with Disabilities Act (ADA) requirements and an overall rating of the condition of the site. The individual categories listed on the inspection checklist were: grounds, roads, burial sites, headstones, plaques and features, structures or buildings, safety, room, bed, pool, drainage, utilities, ADA, and other. These items were rated as satisfactory or unsatisfactory with remarks as necessary to explain the rating. The overall condition of the site was rated as excellent, good, or fair. An excellent site had no discrepancies and was clean and well maintained. A good site had minor discrepancies; however, it too was fairly clean and well maintained. A fair site required repair or maintenance. This may be ground maintenance, structural repair, replacement of the memorial or general cleaning and upkeep.

Repair and Maintenance Findings

The assessment teams evaluated twenty sites. Two cemeteries were rated excellent which are the Hilo Veterans Cemetery No. 1 and the West Hawaii Cemetery; three Memorial Plaques were rated excellent, which are the 29th Infantry Memorials, the Keaukaha Military Reservation Armory Memorial Plaque and the Pahala Memorial Plaque. Lastly, the Yukio Okutsu Veterans Long Term Care Home in Hilo was rated in excellent overall condition. A total of six State Memorials were rated overall in excellent condition.

Nine sites were rated overall in good condition in need of a few repairs. That would include three cemeteries, the Hawaii State Veterans Cemetery in Kaneohe, Hilo Veterans Cemetery No. 2 and the Lanai Veterans Cemetery. The Interstate H-2 Veterans Memorial Highway on Oahu was rated in good condition. Lastly, five memorial monuments were rated in good overall condition which includes the Armed Forces Eternal Flame, the Korean and Vietnam War Memorials, the WWII Monument, the Varsity Victory Volunteers Sculpture, and the General Lyman Airport Memorial.

Finally, a total of five sites were rated in fair condition and in need of major repairs. Among them were three veterans cemeteries which are the Makawao Veterans Cemetery on Maui, the Hoolehua Veterans Cemetery on Molokai and the Kauai Veterans Cemetery. The Kauai Veterans Memorial Hospital and the Waimea War Memorial Swimming Pool on Kauai were rated in fair condition.

Following are the individual inspection checklist and photographs of each site. A review of these materials will provide a detailed assessment of each State war memorial, the freeway, veterans' cemeteries, memorial hospital, long term care home and memorial swimming pool.

Inspection Checklist

Name of Site: **Armed Forces Eternal Flame**

Date: February 25, 2014

Type: X Memorial Island: X Oahu

Description of Site: The monument is located in the State Capitol area adjacent to Washington Place and the State Department of Health building. The Eternal Flame is black stone sculpture in a Royal Palm courtyard. It is dedicated to the men and women of the State of Hawaii who served in the armed services of the United States. This monument is maintained by the State Departments of Accounting and General Services and Land and Natural Resources.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.		X	Weeds are growing between the cement slabs; crack in cement in front of the eternal flame.
2. Plaques or Features	Cleaned and maintained with no broken items.	X		The steel sculpture is a little withered in color. There are spots of gray.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
4. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.
5. Utilities	Has water and electricity.		X	Electrical outlet cover is broken and exposed to rain.
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.
7. Other	General observation per monument.		X	Upkeep of the back hedge needs to be trimmed and maintained.
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained.		Good	Weeds growing in the cement needs to be pulled; electrical outlet cover need to be fixed/replaced.

	Fair site required repairs or maintenance.				
--	---	--	--	--	--








DEDICATED TO THE MEN AND WOMEN
OF THE STATE OF HAWAII
OF THE ARMED FORCES OF THE UNITED STATES











Inspection Checklist

Name of Site: **Korean and Vietnam Memorials**

Date: February 25, 2014

Type: X Memorial Island: X Oahu

Description of Site: The Korean and Vietnam War Memorials are located on the grounds of the State Capitol Building and comprised of black marble stone blocks mounted against a moss rock wall. The names of the fallen heroes are inscribed on each block. The site is maintained by the Department of Accounting and General Services.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.		X	Few weeds in hedges; path made through the hedge in front of Korean Memorial; smell of urine.
2. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.		X	Vagrant sleeping on cement in Korean Memorial area.
4. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.
5. Utilities	Has water and electricity.	X		In compliance.
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.
7. Other	General observation per monument.	X		The Memorial stands in an honorable manner.
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.		Good	Vagrants are using the hedge for bathroom use. Security need to be more proactive. It's a place of RESPECT AND HONOR.













Inspection Checklist

Name of Site: **World War II Monument**

Date: January 27, 2014

Type: X Memorial Island: X Oahu

Description of Site: This World War II monument is located on the corner of King and Punchbowl streets. It is a white stone tower mounted on a four-foot base surrounded by a link chain fence. The inscription on the tower reads, "In honor of all Americans of Hawaii who died in this World War that the beauty and freedom of our land might be preserved for all humanity." This monument is owned and maintained by the State Department of Accounting and General Services.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.		X	Due to graffiti at front bottom of outside fence. Weeds, grass and brushes need cutting.
2. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
4. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.
5. Utilities	Has water and electricity.			N/A
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance
7. Other	General observation per monument.		X	Problems due to location to major bus stop/transfer point. Plastic bag hanging on fence. Some of the decorative tops to fence missing. Description above needs to change chain link to wrought iron fencing.
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor		Good	Removal of graffiti. Lawn manicure with pulling of weeds, cutting of grass and hedges.

	<p>discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.</p>			
--	---	--	--	--



A black and white photograph of a monument. The monument is a tall, rectangular pillar with a base, set against a cloudy sky. To the left of the monument are several palm trees of varying heights. In the background, a large, dark building with a classical architectural style is visible. The overall scene is in silhouette, with the sky being the brightest part of the image.

IF HONOR
OF ALL
AMERICANS
OF HAWAII
WHO DIED
IN THE
WORLD WAR
MAY THE
LANDS AND
TERRITORY
OF OUR LAND
RIGHT BE
RECEIVED
BY ALL
HUMANITY





Inspection Checklist

Name of Site: **Varsity Victory Volunteers Sculpture**

Date: February 25, 2014

Type: X Memorial Island: X Oahu

Description of Site: The Varsity Victory Volunteers Sculpture is located at the University of Hawaii, Student Services Center. This sculpture is mounted on a wood framed plastic laminated base. It is dedicated to the Nisei volunteers who worked on military construction projects. In 1942, these volunteers formed the nucleus of the 442nd Regimental Combat Team. The State Foundation on Culture and the Arts erected the sculpture. The Sculpture was inspired by the Japanese folk story, "Momotaro," the peach boy who came from humble beginnings who overcame great odds and adversity to save his village. This sculpture is owned and maintained by the University of Hawaii.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.		X	Walkway in front of sculpture is worn and withered.
2. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.		X	Base of sculpture is broken on the corner; need to be fixed. Patrons can get cut when mistakenly hit with foot.
4. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.			N/A
5. Utilities	Has water and electricity.			N/A
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.			N/A
7. Other	General observation per monument.			
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well -		Good	Sculpture base needs to be repaired. Walkway need to be repaved.

	maintained. Fair site required repairs or maintenance.			
--	---	--	--	--





13c

State Foundation on Culture and the Arts

Art in Public Places

BUMPEI AKAJI

WW

Copper, Bronze, 1995

This tribute to the Varsity Victory Volunteers symbolizes the essence of courage and dedication. Its pure sculptural form was inspired by the Japanese folk story of *Momotarō*, the peach boy from humble beginnings who overcame great odds and adversity to save his village.

Bumpei Akaji was born in Lawai, Kauai in 1921.

State of Hawaii

Department of Accounting and General Services



Inspection Checklist

Name of Site: **Hawaii State Veterans Cemetery**

Date: January 25, 2014

Type: X Cemetery Island: X Oahu

Description of Site: The Cemetery is located in Kaneohe adjacent to Hawaii Memorial Park. It is a 123 acre complex with an administration building, flag plaza, maintenance facility, committal shelter, columbaria and water tank. The Cemetery was built in 1990 and completed in 1993.

The Cemetery is owned and maintained by the State Office of Veterans Services.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		Well maintained; cut lawns.
2. Roads	Paved with no potholes and no flooding.	X		Well maintained; no debris or large potholes.
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.	X		Well maintained.
4. Headstones	Intact, not broken or in need of replacement. In proper position.	X		In compliance.
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.		X	Some weeds in cement; black stains on top of edge of building; see pictures.
6. Plaques or Features	Cleaned and maintained with no broken items.		X	Plaque/sign needs to be fixed; missing letters; holes and dirt in cement sign.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.	X		In compliance.
8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
9. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.
10. Utilities	Has water and electricity.	X		In compliance; inspection was during the day.
11. ADA	Meets ADA requirements for bathrooms, parking,	X		In compliance.


	and access routes.			
12. Other	General observation per monument.			Minor fix to details of the cemetery.
		E	G	F Remarks:
13. Over all condition of Site	<p>Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.</p>		Good	Just need to repair the cement sign and clean the dirt from the sign. Need to pull the weeds in the cement at the Memorial above the cemetery grounds.



01/24/2014



01/24/2014



01/24/2014

01/24/2014





DEDICATED TO ALL MEN AND WOMEN
WOUNDED IN ALL OUR WARS

WOUNDED
IN ALL OUR
WARS
MILITARY BRANCHES
OF THE UNITED STATES
OF AMERICA

MY STONE IS RED FOR
THE BLOOD THEY SHED
THE MEDAL I BEAR
IS MY COUNTRY'S WAY
TO SHOW THEY CARE
IF I COULD BE SEEN
BY ALL MY HAND
MAYBE PERCE WILL
COME IN MY LIFETIME

FACTORY DEPT. OF ARMY
MILITARY BRANCH OF THE UNITED STATES

01/24/2014

01/24/2014





Honor Circle

Dur Y Circle

01/24/2014

Inspection Checklist

Name of Site: **29th Infantry Brigade Memorials**

Date: January 27, 2014

Type: X Memorial Island: X Oahu

Description of Site: These Memorials are located at the 29th Brigade Headquarters in Kalaeloa. There are two 3 by 2 feet bronze plaque mounted on a freestanding moss rock. The Memorials are dedicated to the gallant men of the 29th Infantry Brigade who served with honor and distinction and gave their lives while serving the country during the Vietnam and Gulf War for all humanity." It is owned and maintained by the State Department of Defense.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		Everything was in order.
2. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		N/A
4. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		N/A
5. Utilities	Has water and electricity.	X		N/A
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		N/A
7. Other	General observation per monument.			Memorial is clean and maintained.
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.	Excellent		Plaque still looks new.

Inspection Checklist

Name of Site: **Interstate H-2 Veterans' Memorial Highway** Date: January 27, 2014

Type: Memorial Island: Oahu Highway

Description of Site: This Highway extends from Pearl City to Wahiawa. "America became a great nation because every time our belief and ideals have been threatened, our soldiers have stepped forward to defend them. They risked their lives for the freedoms we enjoy today, and we will be eternally grateful." Governor Benjamin J. Cayetano, October 28, 2002. The highway is owned and maintained by the State Department of Transportation, Highways Division.

Ownership: State County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Roadway	Paved with no potholes and no flooding.	X		Weeds need to be cut.
2. Side of road	Cleaned and maintained.	X		In compliance.
3. Sign or Features	Cleaned and maintained with no broken items.	X		In compliance.
4. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
5. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		Green barricades surrounding drains on left side of north bound lanes?
6. Utilities	Has water and electricity.		X	A few lights out near Wahiawa exit.
7. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.
8. Other	General observation per monument.		X	Asphalt patch is broken, creates rough uneven surface for motorist.
		E	G	F Remarks:
9. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.		Good	Few repairs; replace light bulbs and repave broken asphalt on parts of road.

Inspection Checklist

Name of Site: **Hilo Veterans Cemetery No. 1**

Date: January 22, 2014

Type: X Cemetery Island: X Hawaii

Description of Site: The Hilo Veterans Cemetery No. 1 is a five acre site situated in the northern section downtown Hilo. The cemetery is in full capacity, except for a few reserved plots and niches in the columbarium. The 442nd Veterans Club, Hilo Chapter, completed the committal shelter in 1951. It was constructed to honor those killed in action in WWII. There are two plaques on the flagpole. One honors those killed in the sinking of the USS Transport Frank. The other honors those killed in the Korean Conflict. The names of the WWII, Korean War and Vietnam War veterans are listed on an Honor Roll within the committal shelter. The cemetery is maintained by the County of Hawaii, Department of Parks and Recreation.

Ownership: State X County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		In compliance.
2. Roads	Paved with no potholes and no flooding.	X		In compliance.
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.	X		In compliance.
4. Headstones	Intact, not broken or in need of replacement. In proper position.	X		In compliance
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.	X		Not being used because of vandalism.
6 Plaques or Features	Cleaned and maintained with no broken items.		X	Very dull looking from age and weather. Unable to read the words on plaque.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.	X		In compliance.
8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
9. Drainage	Proper maintenance of drywalls, culverts,	X		In compliance.

	downspouts, etc., and good site drainage.			
10. Utilities	Has water and electricity.	X		In compliance
11. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance
12. Other	General observation per monument.	X		Cemetery is well maintained with minor fixes.
		E	G	F Remarks:
13. Over all condition of Site	<p>Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.</p>	Excellent		Need to remove graffiti and refurbish plaques.



(1) Veteran Cemetery #1 Entrance



(2) Veteran Cemetery #1 Entrance



(3) Veteran Cemetery #1



(4) Veteran Cemetery #1



(5) Veteran Cemetery #1 Parking Lot



(6) Veteran Cemetery #1 Pavilion

Hawaii County



(7) Veteran Cemetery #1



(8) Veteran Cemetery #1



(9) Veteran Cemetery #1 Plaque for 100th Infantry Battalion



(10) Veteran Cemetery #1 Plaque for 442nd Regimental Combat Team



(11) Veteran Cemetery #1 Plaque for the Military Intelligence Service



(12) Veteran Cemetery #1 Plaque for the Korean Conflict

Hawaii County




(13) Veteran Cemetery #1 Plaque for Comrades killed in the USS Transport Frank Sinking



(14) Veteran Cemetery #1 Pavilion



(15) Veteran Cemetery #1 Ramp to the Pavilion



(16) Veteran Cemetery #1 Sign with Completion date of Pavilion 12/23/51



(17) Veteran Cemetery #1 World War II Hawaii County Roll of Honor

Hawaii County



(18) Veteran Cemetery #1 Korean War Roll of Honor



(19) Veteran Cemetery #1 Entrance to Rest Rooms



(20) Veteran Cemetery #1



(21) Veteran Cemetery #1 Pavilion area



(22) Veteran Cemetery #1 Headstones



(23) Veteran Cemetery #1 Headstones



(24) Veteran Cemetery #1 Headstones

Hawaii County

Inspection Checklist

Name of Site: **Hilo Veterans Cemetery No. 2**

Date: January 22, 2014

Type: X Cemetery Island: X Hawaii

Description of Site: The Hilo Veterans Cemetery No. 2 is next to the Hilo Veterans Cemetery No. 1. The cemetery is on a seven acre parcel and was opened in 1979 to accommodate veterans, and their dependents for burials. The cemetery is owned by the County of Hawaii and maintained by the Department of Parks and Recreation.

Ownership: State X County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		In compliance.
2. Roads	Paved with no potholes and no flooding.	X		In compliance.
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.	X		In compliance.
4. Headstones	Intact, not broken or in need of replacement. In proper position.	X		In compliance.
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.	X		Outstanding.
6. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.	X		Pavilion adequately meets the needs of the cemeteries.
8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
9. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.		X	Grounds showed ponding, poor drainage and erosion.
10. Utilities	Has water and electricity.	X		In compliance.
11. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.

12. Other	General observation per monument.		X	Needs gravesite locator and pamphlets. Turf trimming, height & alignment of the gravesite markers in the burial needs to be improved
		E	G	F Remarks:
13. Over all condition of Site	<p>Standard:</p> <p>Excellent site has no discrepancies. It was clean and well maintained.</p> <p>Good site had minor discrepancies; however, it was cleaned and well - maintained.</p> <p>Fair site required repairs or maintenance.</p>		Good	Need to install drainage system. See remarks above.



(25) Veteran Cemetery #2 Entrance



(26) Veteran Cemetery #2 Maintenance Facility



(27) Veteran Cemetery #2



(28) Veteran Cemetery #2



(29) Veteran Cemetery #2 Disabled American
Veteran's Memorial

Hawaii County



(30) Veteran Cemetery #2 DAV Memorial

Inspection Checklist

Name of Site: **Yukio Okutsu Veterans Home**

Date: January 22, 2014

Type: X Nursing Home

Island: X Hawaii

Description of Site: This Veterans Nursing Home built in 2004 is located in Hilo, next to the Hilo Hospital. It is a 95 bed nursing care facility. Owned and operated by the Hawaii Health Systems. It was named after Medal of Honor recipient Yukio Okutsu. The Home opened its doors for operation on November 12, 2007. Veterans Home is owned and maintained by State Department of Health, Hawaii Health System Corp.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		In compliance.
2. Building	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.	X		In compliance.
3. Rooms	Clean and maintained, good general housekeeping. No structural deficiencies.	X		In compliance.
4. Beds	Clean, safe and sturdy.	X		In compliance.
5. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
6. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.
7. Utilities	Has water and electricity.	X		In compliance.
8. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.
9. Other	General observation per monument.	X		Pictures provided.
		E	G	F Remarks:
10. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was	Excellent		Veterans are well taken care of by staff and the administration.

	<p>clean and well maintained.</p> <p>Good site had minor discrepancies; however, it was cleaned and well - maintained.</p> <p>Fair site required repairs or maintenance.</p>			
--	--	--	--	--



(31) Yukio Okutsu Veterans Home Entrance



(32) Yukio Okutsu Veterans Home Front Grounds



(33) Yukio Okutsu Veterans Home Loading/Unloading Area



(34) Yukio Okutsu Veterans Home Front Entrance



(35) Yukio Okutsu Veterans Home Hallway



(36) Yukio Okutsu Veterans Home Hall

Hawaii County



(37) Yukio Okutsu Veterans Home Bedroom



(38) Yukio Okutsu Veterans Home Bedroom



(39) Yukio Okutsu Veterans Home Hall/Dining Area



(40) Yukio Okutsu Veterans Home Grounds

Inspection Checklist

Name of Site: **General Lyman Airport Memorial**

Date: January 22, 2014

Type: X Memorial Island: X Hawaii

Description of Site: This Memorial is located at the Hilo Airport. The monument honors Brigadier General Albert Kualii Brickwood Lyman. He is honored for being the first person of Hawaiian ancestry to attain the rank of General. The monument is a 4 by 4 feet bronze plaque mounted on a moss rock wall and landscaped with indigenous plants. It is State owned and maintained by the Department of Transportation.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		In compliance.
2. Plaques or Features	Cleaned and maintained with no broken items.	X		Although the memorial is maintained and cleaned, the 4' x 4' base need to be restored.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.			N/A
4. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.			N/A
5. Utilities	Has water and electricity.			N/A
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.			N/A
7. Other	General observation per monument.			Very nice and readable.
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.		Good	Base of Memorial need to be repaired.



(41) General Lyman Airport Memorial
Back of Monument



(42) General Lyman Airport Memorial
Back of Monument



(43) General Lyman Airport Memorial
Plaque/Monument



(44) General Lyman Airport Memorial
Plaque/Monument



(45) General Lyman
Airport Memorial
Plaque/Monument



(46) General Lyman
Airport Memorial
Plaque/Monument

Hawaii County



(47) General Lyman Airport Memorial
Plaque/Monument



(48) General Lyman Airport Memorial
Plaque/Monument



(49) General Lyman Airport Memorial
Plaque/Monument

Inspection Checklist

Name of Site: **Keaukaha Military Reservation (KMR) Armory Plaque** Date: January 22, 2014

Type: X Memorial Island: X Hawaii

Description of Site: The 18 inches by 24 inches bronze plaque is mounted on the wall of the KMR Armory. It honors Hawaii Army National Guard comrades of the Vietnam War who died during that conflict. It reads: "In memory of the gallant men of the 29th Infantry Brigade from Hawaii who served with honor and distinction and gave their lives while in service of their country." It is State owned and maintained by the State Department of Defense.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Building	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.			N/A
2. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.			N/A
4. Walls	Intact, unblemished and maintained.			N/A
5. Utilities	Has water and electricity.			N/A
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.			N/A
7. Other	General observation per monument.			
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.	Excellent		Cleaned and maintained.



(50) Keaukaha Military Reservation
Armory Plaque within showcase



(51) Keaukaha Military Reservation
Armory Plaque Showcase



(52) Keaukaha Military Reservation
Armory Outside Memorial/Plaque



(53) Keaukaha Military Reservation
Armory Plaque

Inspection Checklist

Name of Site: **Pahala Memorial**

Date: January 24, 2014

Type: Memorial Island: Hawaii

Description of Site: The Pahala Memorial was a plaque mounted on the fence of the Pahala School tennis court. The plaque was made of sheet metal in the shape of a shield honoring nine veterans. It is State owned and maintained by the Department of Accounting and General Services.

Ownership: State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.			N/A
2. Plaques or Features	Cleaned and maintained with no broken items.	X		Plaque is well maintained and readable.
3. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.			N/A
4. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.			N/A
5. Utilities	Has water and electricity.			N/A
6. ADA	Meets ADA requirements for bathrooms, parking, and access routes.			N/A
7. Other	General observation per monument.			
		E	G	F Remarks:
8. Over all Condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.	Excellent		Plaque is very new.



(54) Pahala Memorial Plaque



(55) Pahala Memorial Plaque



(56) Pahala Memorial Plaque



(57) Pahala Memorial Plaque




(58) Pahala Memorial Plaque/Playground

Hawaii County



(59) Pahala Memorial Grounds



(60) Pahala Memorial Grounds

Inspection Checklist

Name of Site: **West Hawaii Veterans Cemetery**

Date: February 2, 2014

Type: X Cemetery Island: X Hawaii

Description of Site: The West Hawaii Veterans Cemetery was dedicated on November 9, 1997, and is located in the North Kona District of the County of Hawaii, approximately 12 miles north of Kailua, Kona. Access to the cemetery is from the Queen Kaahamanu Highway. The cemetery is built on Pu'u O'o volcanic cinder cone, 559 feet above sea level, comprising nearly 14 acres of A'a lava rock. In addition to space for about 10,000 gravesites there are flagpoles, a parking lot, and a committal shelter. The site is landscaped with xeroscopic vegetation. It is owned by the County of Hawaii and maintained by the Parks and Recreation.

Ownership: X State County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.		X	Damaged sod.
2. Roads	Paved with no potholes and no flooding.	X		Generally in excellent condition and pleasantly accessible to all cemetery areas.
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.		X	B field #2 lumpy 2 year old burials.
4. Headstones	Intact, not broken or in need of replacement. In proper position.	X		Aligned well.
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.	X		Very well sited in a pleasant environment and well maintained.
6. Plaques or Features	Cleaned and maintained with no broken items.	X		The plaques are most appropriate for the cemetery and the reforestation description is very well prepared, appropriate and fits well with the professionally tasteful and respectful design and organization of the cemetery.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies.	X		Well maintained.

	Roof & gutter condition.			
8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
9. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.
10. Utilities	Has water and electricity.	X		In compliance.
11. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.
12. Other	General observation per monument.	X		Landscaped trees and grassed area in all three burial fields present an overall satisfactory appearance but splotches of sod damage detracts from the overall appearances.
		E	G	F Remarks:
13. Over all condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well-maintained. Fair site required repairs or maintenance.	Excellent		Generally presents an excellent impression of a well-designed and maintained cemetery.



Image 227

Cemetery sign at entrance on highway




Image 229

Access road up to the cemetery



Image 231

Inner "goat gate"- remote opener



Image 232

Central roadway & visitor parking



Image 241

Planned POW/MIA & ash scattering area



Image 327

Outer gate - Cemetery hours sign



Image 2212

Committal Shelter - view from South




Image 2192

Concrete walkway - From Committal shelter



Image 2200

Concrete walkway to Committal Shelter



Burial field #1 with Columbaria area in back Image 356



Burial field #2 with Committal Shelter in back Image 235



Burial field #3 - Urn burial Image 218



Image 184

B Fld #2 Lumpy 2 year old burials



Image 210

Damaged sod - South of Committal Shelter



Image 185

Burial field #2 Sod Replace. new burial



Image 213

Damaged sod - East end of B Fld #1




Image 361

Damaged sod - NE end of B Fld #1



Images 376

Columbaria area - cement walk area




Image 2190

Columbaria area - cement walk area



Image 2188

Military service plaques - Committal shelter



Image 369

Reforestation sign below planting area

Inspection Checklist

Name of Site: **Makawao Veterans Cemetery**

Date: February 7, 2014

Type: X Cemetery Island: X Maui

Description of Site: The Makawao Veterans Cemetery is a 10 acre site located in Upcountry Maui. Entry into the cemetery is from Baldwin Avenue. The cemetery was established in January 29, 1951 to accommodate Maui veterans. Upgrades and renovations include a columbarium, restrooms, and a committal shelter. The AJA Veterans Club, Maui Chapter dedicated an 18 inches by 24 inches bronze plaque mounted on most rock veneer located adjacent to the committal shelter and a 5 feet by 4 feet granite headstone mounted in concrete to honor the MIA from WWII and the Korean War Veterans. This cemetery is owned and maintained by the County of Maui, Department of Public Works.

Ownership: State X County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		In compliance.
2. Roads	Paved with no potholes and no flooding.		X	Roads are cracked and unmarked.
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.	X		In compliance.
4. Headstones	Intact, not broken or in need of replacement. In proper position.	X		In compliance.
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.	X		In compliance.
6. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.	X		In compliance.
8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.		X	Walkways are uneven and overgrown with grass.
9. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.

10. Utilities	Has water and electricity.	X		In compliance.
11. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.
12. Other	General observation per monument.		X	Flag is worn and withered.
		E	G	F Remarks:
13. Over all condition of Site	<p>Standard:</p> <p>Excellent site has no discrepancies. It was clean and well maintained.</p> <p>Good site had minor discrepancies; however, it was cleaned and well - maintained.</p> <p>Fair site required repairs or maintenance.</p>			Fair - Cemetery needs major repairs with their sidewalks and roads.

Inspection Checklist

Name of Site: **Hoolehua Veterans Cemetery**

Date: February 6, 2014

Type: X Cemetery Island: X Molokai

Description of Site: The cemetery is about a one acre burial site with restroom facilities. A low rock wall fronts the property. A chain link fence encloses the remaining three sides of the cemetery. The cemetery was opened in August 1950. It is owned and maintained by the County of Maui, Department of Public Works.

Ownership: State X County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		In compliance.
2. Roads	Paved with no potholes and no flooding.	X		Roads are maintained and the markings are clear
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.	X		In good condition and in compliance.
4. Headstones	Intact, not broken or in need of replacement. In proper position.	X		In compliance
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.	X		Well maintained and in compliance.
6. Plaques or Features	Cleaned and maintained with no broken items.	X		In compliance.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.		X	Bathroom facility needs to be cleaned and maintained. Sinks are plugged with moldy water and rust.
8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.		X	Unsanitary bathroom sinks.
9. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.		X	Bathroom sink need to be fixed. Water cannot drain.
10. Utilities	Has water and electricity.	X		In compliance.
11. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.

12. Other	General observation per monument.			
		E	G	F Remarks:
13. Over all condition of Site	<p>Standard:</p> <p>Excellent site has no discrepancies. It was clean and well maintained.</p> <p>Good site had minor discrepancies; however, it was cleaned and well - maintained.</p> <p>Fair site required repairs or maintenance.</p>			<p>Fair - Bathroom sinks need to be repaired in order to meet the needs of the veterans. Draining of sink water especially needs to be immediately repaired.</p>



32a











Inspection Checklist

Name of Site: **Lanai Veterans Cemetery**

Date: February 6, 2014

Type: X Cemetery Island: X Lanai


Description of Site: The Lanai Veterans Cemetery was dedicated on March 31, 1997. It overlooks West Lanai above the Lodge of Ko'ele. The one acre site was donated by the Lanai Company and now includes a committal shelter, water tank and flagpole. The site will meet the needs of Lanai veterans for many years. It is owned and maintained by the County of Maui, Department of Public Works.

Ownership: State X County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.		X	Centipede grass is overgrown; regular grass killed by drought. Plenty weeds and few bare spots.
2. Roads	Paved with no potholes and no flooding.		X	Roads are good but park stall lines need to be remarked-faded; could use more stalls.
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.	X		Well maintained.
4. Headstones	Intact, not broken or in need of replacement. In proper position.	X		All plaques are in compliance.
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.	X		New slab and gravel installed.
6. Plaques or Features	Cleaned and maintained with no broken items.		X	Flag is new; flagpole winch cover is broken.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.		X	Rusted bolts and nails on windward side of building. Hardware under roof is rusted; windows need cleaning; concrete patio needs repainting. Men and Women bathroom signs are missing; some dry rot; roof is flat with lots of organic growth on top. Vent screens rusted through.


8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
9. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.		X	Temporary gravel was placed to dry water next to walkway; big pond of water in drive way because of no drainage.
10. Utilities	Has water and electricity.		X	No water, tank next to cemetery is empty.
11. ADA	Meets ADA requirements for bathrooms, parking, and access routes.	X		In compliance.
12. Other	General observation per monument.	X		Beautiful grounds however needs repair.
		E	G	F Remarks:
13. Over all condition of Site	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.		Good	Tree next to side walk need to be removed because of the roots growing under the building and sidewalk will crack the walk way and concrete foundation.

VETERANS
CEMETERY























34j



Inspection Checklist

Name of Site: **Kauai Veterans Cemetery**

Date: January 30, 2014

Type: X Cemetery Island: X Kauai

Description of Site: The Kauai Veterans Cemetery is comprised of 15 acres located in Hanapepe, Kauai. The cemetery was opened in 1950 to accommodate the burial of Kauai's veterans and their family members. Recent renovations include upgrading the restrooms, committal shelter, and expanding the cemetery by five acres. It is owned and maintained by the County of Kauai, Department of Parks and Recreation.

Ownership: State X County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.		X	Grass is dried with mostly weeds; bare spots with dirt only. Poor maintenance on grounds.
2. Roads	Paved with no potholes and no flooding.		X	Roads have a long crack; need to be repaved.
3. Burial Sites	No sinking burial sites. Old flowers and cans disposed.		X	There are a few sunken graves.
4. Headstones	Intact, not broken or in need of replacement. In proper position.		X	Plaques on graves are sunken. Need to be aligned.
5. Columbarium	Intact, not broken or in need of replacement. In proper position. Old flowers and cans disposed.	X		In compliance.
6. Plaques or Features	Cleaned and maintained with no broken items.		X	Plaques and features does not meet the requirement.
7. Structures or Buildings	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.		X	Very poor; need painting and repair. There is wood rot.
8. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
9. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.		X	There are flooding in areas of the cemetery.
10. Utilities	Has water and electricity.	X		In compliance.

11. ADA	Meets ADA requirements for bathrooms, parking, and access routes.		X	Bathrooms are not ADA compliant.
12. Other	General observation per monument.		X	Cemetery is poorly maintained.
		E	G	F Remarks:
13. Over all condition of Site	<p>Standard:</p> <p>Excellent site has no discrepancies. It was clean and well maintained.</p> <p>Good site had minor discrepancies; however, it was cleaned and well - maintained.</p> <p>Fair site required repairs or maintenance.</p>			<p>Fair - Cemetery grounds need to be maintained and repaired. Bathrooms need to have ADA rails installed.</p>



36a







36d



36

36a

4







Inspection Checklist

Name of Site: **Kauai Veterans Memorial Hospital**

Date: January 29, 2014

Type: X Hospital

Island: X Kauai

Description of Site: This Hospital is a State facility built in 1978 in honor of World War II veterans. It is a 49 bed community Hospital operated by the State to serve veterans and the others in the community. It is owned and maintained by the State Department of Health.

Ownership: X State ___ County

Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Grounds	Grass is cut, no rubbish or debris on ground. Good landscaping.	X		In compliance.
2. Building	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.		X	Exterior in need of repainting.
3. Rooms	Clean and maintained, good general housekeeping. No structural deficiencies. Roof & gutter condition.	X		In compliance.
4. Beds	Clean, safe and sturdy.		X	Beds need to be replaced and upgraded.
5. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.	X		In compliance.
6. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.		X	Two toilets in long term care room are clogged; unable to use. Unsanitary.
7. Utilities	Has water and electricity.		X	All exterior lights need to be changed to LED. Electric utility room box need to be replaced; rusted substandard, must upgrade.
8. ADA	Meets ADA requirements for bathrooms, parking, and access routes.		X	In compliance.
9. Other	General observation per monument.		X	Hallway floor tile made of asbestos; tile is cracked and need to be replaced.
		E	G	F Remarks:

<p>10. Over all Condition of Site</p>	<p>Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.</p>			<p>Fair - Hospital interior and exterior needs to be majorly repaired to including the utility room electrical box.</p>
--	---	--	--	--



384

M- AIR CONDITIONER PANEL BY JANITOR SUPPLY ROOM ACROSS NURSES' STATION

D- JANITOR SUPPLY ROOM PANEL BY KITCHEN HALLWAY

X-RAY MACHINE

P- CONTROL PANEL IN THIS ROOM

ALL WIRING TO EMERGENCY POWER SECTORS TO TURN OFF EMERGENCY POWER SUPPLY BY SWITCH ROOM

B- NEW WIRE

L- PANEL

C- KUKAHA CORRIDOR PANEL

B- PORTABLE X-RAY ROOM PANEL

R- AIR CONDITIONING

K- IN KITCHEN

A
EN POI

OUR WALL



2

2

2

2

OR

OB

A

EM POWER

2

2


2

2

2

2





Inspection Checklist

Name of Site: **Waimea War Memorial Swimming Pool**

Date: January 29, 2014

Type: X Swimming Pool Island: X Kauai

Description of Site: The Waimea War Memorial Swimming Pool is located at the Waimea High School. It was dedicated in 1955 to honor the brave soldiers from Kauai. A 12 inches by 24 inches plaque is mounted on the building fronting the swimming pool. It is owned and maintained by the State Department of Accounting and General Services.

Ownership: X State ___ County


Maintenance Item	Standard	Sat.	Unsat.	Remarks
1. Pool	Not cracked or broken.		X	Concrete badly cracked around pool.
2. Safety	No hazardous conditions such as uneven sidewalks or fire conditions.		X	Walkway very slippery when wet.
3. Drainage	Proper maintenance of drywalls, culverts, downspouts, etc., and good site drainage.	X		In compliance.
4. Utilities	Has water and electricity.	X		In compliance.
5. ADA	Meets ADA requirements for bathrooms, parking, and access routes.		X	Restrooms do not have any rails or stall privacy.
6. Plaques	Cleaned and maintained with no broken items.	X		In compliance.
7. Other	General observation per monument.		X	Exterior and interior need repainting.
		E	G	F Remarks:
8. Over all Condition of Sit	Standard: Excellent site has no discrepancies. It was clean and well maintained. Good site had minor discrepancies; however, it was cleaned and well - maintained. Fair site required repairs or maintenance.			Fair - Facility needs major repairs.

WAIMŪA WAR MEMORIAL. SWIMMING POOL

1955

IN MEMORY OF OUR BRAVE PATRIOTS WHO GAVE
THEir LAST FULL MEASURE OF DEVOTION
DURING THE WAIMŪA WAR,
THEir FRIENDS AND COUNTRYMEN OF KAUAĪ







39d